

July 18, 2020

Robert Oakes HVAC

121 Tylerstone Dr.
Fuquay- Varina , NC 27526NC
Lic # 31425 H2, H3
919-268-1827

Customer: George Benscoter

42 Del Mar Ct Fuquay Varina, NC

Diagnosis: compressor windings are open. Bad compressor. Small leak in evaporator coil
recommend system replacement.

Parts Compressor	1200.00
Evaporator coil	450.00
R-22 refrigerant 13 lbs	1300.00
Labor	1500.00
Tax	275.00
Total	4675.00

Due to age of system 16 years and it being a 10 SEER r22 system. Recommend replacement with 3 ½ ton Goodman 14 SEER system. Estimate 5300.00.