

AUTO-LAB OF LANSING
State #F-165931/ Store#114
5551 S PENNSYLVANIA
Lansing, MI 48911
Phone#517-394-1314 Fax# 517-580-7425

MIRELES, WILLIAM

Work Order# 110768 11/3/2022
 2014 V6 3.6L 3564 EHM2516
 Chevrolet Vin 1GNKRHKD2EJ338988
 Traverse LT

Mileage
151801

Lansing, MI 48911
 Cell 517-619-7703

WAS TOLD BY DICE AND OTHER SHOP THAT NEEDS TCM THEN TOOK VEHICLE HOME AND IT DUMPED TRANS FLUID EVERYWHERE NOW WILL NOT MOVE. CUSTOMER HAS WYNNS WARRANTY. PLEASE CHECK AND ADVISE.

#106867717
 #844-826-8072 fax #

AAA INSPECTION	*NO CHARGE*
-----------------------	--------------------

LABOR	0.2hrs
PERFORM 33 POINT INSPECTION OF	
VEHICLE	

TRANSMISSION DRIVABILITY	106.20 Group Total
---------------------------------	---------------------------

LABOR	1hrs @106.2/hr 106.20
PRELIMINARY EVALUATION OF THE	
CONDITION OF THE TRANSMISSION	
DRIVABILITY. FURTHER TESTING MAY BE	
NEEDED.	

TRANS COOLER LINE	700.51 Group Total
--------------------------	---------------------------

3	2@	10.02	20.04	MOUNT BOLT	 	LABOR	1.5hrs @106.2/hr	159.30
4	1@	216.67	216.67	RADIATOR MOUNT- RIGHT	 	R&R TRANSMISSION COOLER LINE		
7	1@	216.29	216.29	RADIATOR MOUNT- LEFT	 			
11	1@	11.05	11.05	COOLER LINE CONNECTOR	 			
12	1@	6.95	6.95	COOLER LINE RETAINER	 			
				CLIP	 			
13	1@	8.53	8.53	COOLER LINE BUSHING	 			
ATF	6@	10.28	61.68	SYNTHETIC TRANS FLUID	 			
Parts Subtotal					541.21			

I here by authorize the repair work herein set fourth to be done along with the necessary materials and agree that you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control. I hereby grant you and/ or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/ or inspection. An express garage keeper's lien is hereby acknowledged on the vehicle to secure the amount of repairs thereto. I understand that pursuant to said express garage keeper's lien. I have no right to possession to the vehicle until repairs thereto have been paid in full or until you and/ or your employee have voluntarily released the vehicle to me.

X _____

Parts	541.21
Labor	265.50
SHOP SUPPLIES	48.82
Subtotal	855.53
Sales Tax	35.40
Balance	890.93

AUTO-LAB OF LANSING
State #F-165931/ Store#114
5551 S PENNSYLVANIA
Lansing, MI 48911
Phone#517-394-1314 Fax# 517-580-7425

Work Order# 110768 11/3/2022

Page 2

MIRELES, WILLIAM

2014 V6 3.6L 3564 EHM2516
Chevrolet Vin 1GNKRHKD2EJ338988
Traverse LT

Mileage
151801

Lansing, MI 48911
Cell 517-619-7703

Transmission fluid level extremely low, found severe fluid leak from transmission cooler line at upper fitting to radiator. Found line had been pushed out of connection point. Also found upper radiator mounts are missing, which is what likely caused radiator to shift forward and back and pull cooler line out. Noted damage to hood latch, suspect vehicle had front end damage and was incorrectly repaired previously. Recommend replacement of fitting, upper radiator mounts, and further diagnosis of condition of transmission. Transmission fluid is extremely dark, highly recommend transmission flush if transmission is salvageable. Front right turn signal, running light, and fog light inop. Suspect electrical problem. Engine oil is overfilled by approx. 0.75 quarts